

## RHE DK

### Smoke resin remover



#### Properties

- Highly alkaline foam cleaner
- Removes tar residues, grease, protein and starch
- good wetting and foaming properties

#### Application

RHE DK is a highly alkaline foam cleaner for removing stubborn soiling in the food industry. It powerfully removes the tar residues typical of smoke chambers as well as problematic soiling from grease, protein and starch.

Smoke chamber cleaning:<br>

#### Dosing

##### Smoke resin removal

Addition	Rinse thoroughly with clean water
----------	-----------------------------------

#### Technical data

Density (20°C)	pH-value
1,38	12,5 ; 1 %

#### Titration

Prepare 10 ml application solution and titrate with 0.1 N hydrochloric acid against the indicator phenolphthalein.

Consumption (ml) x 0.11 = concentration in %

#### Notes

Store the product only in the original container and frost-free.  
Direct sunlight should be avoided.  
After removing partial quantities, the container should be resealed.

For commercial use only. This leaflet is for non-binding information only. The information is based on our current knowledge and experience. In any case, the user is obliged to carry out his own tests and trials to check the suitability of the products for his intended processes and purposes. The information in this leaflet does not constitute a guarantee for the quality and durability of the goods to be supplied by us. We reserve the right to make technical changes within the scope of what is reasonable. The current version of the corresponding EU safety data sheet must also be observed.